

LiveScript

Feature updates and known issues

This document describes known issues for this release and includes interim firmware updates that affect product functionality or the user interface as originally documented. Feature enhancements and new functionality that's released after the user documentation was initially published are described here. Refer to this document regularly for the latest update information.

Switchover to Epiphan Cloud

On December 8, 2020, AV Studio was replaced by Epiphan Cloud. The documentation was updated to reflect the new interface. Any devices that were paired to AV Studio migrated over to Epiphan Cloud. You can login to Epiphan Cloud using your AV Studio credentials at: <https://go.epiphan.cloud>

Release 1.0

Inaugural release of the LiveScript transcription system.

Known issues

- The clear transcription button does not work while LiveScript is paused.
Workaround: Unpause the transcription and then select the clear transcription button.
- When connecting the HDMI output from your LiveScript device to Pearl, the video resolution that's set for the HDMI output is not used. The frame size setting for the Pearl channel is used.
Workaround: TBA
- If the system time of your computer and the time synchronization server of your LiveScript device are not synchronized, the transcription timer counter can appear to skip and not count sequentially.
Workaround: TBA